

Property ID:	153	Date: 8-16-03
Address:	3332 LAFAYETTE	Telephone #:
Inspector/Assessor:	CO Certification #: 12860	

Plot Plan:

- BLUE WALLS
- RED TRIM

SDMS Document ID

1051989

LAFAYETTE

		Exterior Walls				Doors/Trim			
		Material	Area	Peel/Chip	XRF (Lead)	Material	Area	Peel/Chip	XRF (Lead)
North South East West	North	STUCCO	—	—	4.8				
	South								
	East								
	West	STUCCO	—	—	1.5				

		Window Trim/Fascia/Soffit				Patios/Decks/Porches			
		Material	Area	Peel/Chip	XRF (Lead)	Material	Area	Peel/Chip	XRF (Lead)
North South East West	North								
	South								
	East								
	West								

		Metal Trim/Gutters/Downspouts				Misc Structures/Garage/Fences			
		Material	Area	Peel/Chip	XRF (Lead)	Material	Area	Peel/Chip	XRF (Lead)
North South East West	North								
	South								
	East								
	West								

August 16, 2005

LBP Assessment Results

Strata Environmental Resource

Time	Site	Component	Substrate	Side	Condition	Color	Floor	Room	Results	Depth In	PbC	PbC Error
8/16/2005 10:48	153	EXT. WALL	PLASTER	WEST	CRACKED	GREY	FIRST	OUTSIDE	Positive	10	1.5	0.3
8/16/2005 10:49	153	RISER	CONCRETE	WEST	PEELING	BROWN	FIRST	PORCH	Negative	3.8	0.03	0.04
8/16/2005 10:50	153	WINDOW SILL	BRICK	WEST	INTACT	RED	FIRST	OUTSIDE	Negative	3.93	0.03	0.04
8/16/2005 10:52	153	WINDOW SILL	BRICK	NORTH	INTACT	RED	FIRST	OUTSIDE	Negative	7.54	0.04	0.07
8/16/2005 10:53	153	WINDOW FRAME	METAL	NORTH	INTACT	RED	FIRST	OUTSIDE	Negative	2.3	0.5	0.2
8/16/2005 10:54	153	EXT. WALL	PLASTER	NORTH	INTACT	WHITE	FIRST	OUTSIDE	Positive	6.83	4.8	0.9
Note: Readings are in mg/cm²												
Painted surfaces not tested were assessed to be in "intact" condition at time of site visit.												

Color Photo(s)

The following pages
contain color that does
not appear in the
scanned images.

To view the actual images, contact
the Region VIII Records Center at
(303) 312-6473.

Property ID # 153 / 3332 Lafayette



West exposure of property